


This form is to be completed with reference to the **Division 5 Asbestos Audit (Report dated: 6-7/4/2015)**

**Asbestos Materials Register**



Surveyor: Roger Moore	Survey Type: Standard Asbestos Sampling Survey	Date of Survey: 6 - 7 May 2015
Site Contact: Amanda Patmore, Principal	Site / Location: Sunshine College Campus 4	Review Date: 7 May 2020

Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments
--------------	-------------	----------	----------------	---------------	------------------	---------------------	-------------------	--------------	-----------	---------------------------	------------	---------------	----------

**ASBESTOS CONTAINING MATERIALS**

**Commerce Wing**

ACM	Rope lining to fireproof filing cabinets	57 Resource	1	DA7323	2 units	1	2	2	0	3	8	A2	Asset numbers 0026 and 4539. Remove both cabinets. Restrict access to cabinets until removed. Refer to Appendix F.
ACM	Cement sheet debris	57 Resource	2, 3	Visual Observation	< 1 m <sup>2</sup>	1	2	1	2	1	7	A3	Debris used as packers to base of filing cabinet. Encapsulated with varnish. Asbestos presumed. Remove when filing cabinets are removed.
ACM	Cement sheet debris	264 Store	4	DA7321	< 1 m <sup>2</sup>	2	1	1	3	2	9	A2	Located on floor, north-east side wall. Remove. Restrict access until removed. Refer to Appendix F.
ACM	Cement sheet clear storey eaves	External	5	Refer to 33538-270 - 274	30 lm	2	1	1	0	0	4	A4	
ACM	Cement sheet clear storey fan infill panel	External		Refer to 33538-278	1 unit	1	1	1	0	1	4	A4	No access due to height. Previously identified in 2004 audit, north of FSCW 55. Assume still present.
ACM	Cement sheet eaves	External	6	33538-275 - 276, 322, 324 - 326, 33 - 335	65 lm	2	1	1	0	0	4	A4	
ACM	Cement sheet debris	External, roof		Refer to 33538-277	Unknown	2	2	1	3	0	8	A2	No access to roof. Previously identified in 2004 audit. Assume still present. Should be inspected when other A1 - A2 items are removed if possible. If still present, remove.

No access was gained within and behind walls, floors, subfloors, tiles, urinals, cavities, ceiling voids, plant/machinery, live electrics or to heights above 3m. Limited access below floor coverings, behind wall coverings and where large amounts of stored items were present. These areas may require further investigation.

**4. Extent of Damage (Condition)**

Variable	Score	Example of score variables
Condition	0	No visible damage
	1	Few scratches / marks broken edges etc.
	2	Significant breakage / many areas of damage revealing loose asbestos fibres
	3	High damage / visible debris

Condition	Comments
NA	Removed
NA	Removed
	No Access
	No Access
	No Access

Additional comments

## Asbestos Materials Register



Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments
Multi Purpose Hall													
ACM	Cement sheet wall	64 Prop Store	7	Refer to 33538-147	35 m <sup>2</sup>	2	1	1	0	1	5	A3	West Wall
ACM	Cement sheet partition wall	64 Prop Store		Refer to 33538-149	25 m <sup>2</sup>	2	1	1	2	1	7	A3	Partition wall. Wall has many areas of localised damage. Remove or encapsulate.
ACM	Cement sheet debris	64 Prop Store	8	DA7325	< 1 m <sup>2</sup>	2	1	1	3	2	9	A2	Debris to floor. Debris is associated with damaged sections of both the partition and west wall. Extremely limited inspection of the floor space due to stored items, presume debris to be throughout 64 Prop Store area. Remove. Restrict access until removed. Refer to Appendix F.
ACM	Cement sheet walls	65 Male Change		Refer to 33538-135, 139, 144	100 m <sup>2</sup>	2	1	1	0	1	5	A3	Including partition walls and cistern panels.
ACM	Cement sheet cubicle partitions	65 Male Change		Refer to 33538-137	16 m <sup>2</sup>	1	1	1	0	1	4	A4	
ACM	Cement sheet ceiling	65 Male Change	9	Refer to 33538-138	20 m <sup>2</sup>	1	1	1	0	0	3	A4	
ACM	Cement sheet walls	66 Female Change	10	Refer to 33538-162, 165, 166	100 m <sup>2</sup>	2	1	1	0	1	5	A3	Including partition walls and cistern panels.
ACM	Cement sheet ceiling	66 Female Change	11	Refer to 33538-164	40 m <sup>2</sup>	1	1	1	0	0	3	A4	
ACM	Cement sheet cubicle partitions	66 Female Change	12	Refer to 33538-163	20 m <sup>2</sup>	1	1	1	0	1	4	A4	
ACM	Cement sheet infill panel	67 Platform	13	Refer to 33538-152	10 m <sup>2</sup>	3	1	1	1	1	7	A3	At high level above stage.
ACM	Cement sheet partition wall	67 Platform	14	Refer to 33538-151	5 m <sup>2</sup>	2	1	1	0	1	5	A3	Partition wall adjoining 64 Prop store. Timber covering. Assume present behind.
ACM	Electrical backing board and fuse lining	67 Platform	15	Visual Observation	1 unit	1	0	1	0	1	3	A4	

Variable	Score	Example of score variables
Condition	0	No visible damage
	1	Few scratches / marks broken edges etc.
	2	Significant breakage / many areas of damage revealing loose asbestos fibres
	3	High damage / visible debris


[illegible]

NORTH CAMPUS SUNSHINE COLLEGE

This form is to be completed with reference to the **Division 5 Asbestos Audit (Report dated: 6-7/4/2015)**



### Asbestos Materials Register



Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments
Multi Purpose Hall													
ACM	Cement sheet walls	68 Steps		Refer to 33538-146	6 m <sup>2</sup>	2	1	1	0	1	5	A3	No access - door nailed / locked shut and obstructed by stored items. Previously identified in 2004 audit. Assume still present.
ACM	Cement sheet walls	68 Steps (Room Above)		Refer to 33538-154	6 m <sup>2</sup>	2	1	1	2	1	7	A3	East, north and west walls. Localised damage. Encapsulate or remove.
ACM	Cement sheet walls	69 Steps	16	Refer to 33538-155	8 m <sup>2</sup>	2	1	1	0	1	5	A3	No access at time of survey, door nailed / locked shut and obstructed by stored items.
ACM	Cement sheet walls	69 Steps (Room Above)	17	Refer to 33538-153	8 m <sup>2</sup>	2	1	1	2	1	7	A3	West, south and east walls. Localised damage. Encapsulate or remove.
ACM	Electrical backing board	69 Steps (Room Above)	18	Visual Observation	1 Item	1	0	1	0	1	3	A4	Located on west wall. Mezzanine level.
ACM	Cement sheet walls	70 CLNR		Refer to 33538-133	10 m <sup>2</sup>	2	1	1	0	1	5	A3	
ACM	Cement sheet ceiling	70 CLNR		Refer to 33538-134	2 m <sup>2</sup>	1	1	1	0	0	3	A4	
ACM	Cement sheet walls	71 CLNR	19	Refer to 33538-160	8 m <sup>2</sup>	2	1	1	0	1	5	A3	
ACM	Cement sheet ceiling	71 CLNR	20	Refer to 33538-161	2 m <sup>2</sup>	1	1	1	0	0	3	A4	
ACM	Cement sheet infill panel	74 Porch		Refer to 33538-175	4 m <sup>2</sup>	2	1	1	0	1	5	A3	Above door.
ACM	Cement sheet infill panel	75 Porch		Refer to 33538-179	1 m <sup>2</sup>	2	1	1	0	1	5	A3	Above door.
ACM	Cement sheet ceiling	76 Chair Store	21	Refer to 33538-169	15 m <sup>2</sup>	1	1	1	0	0	3	A4	
ACM	Cement sheet ceiling	77 Chair Store	21	Refer to 33538-131	25 m <sup>2</sup>	2	1	1	0	0	4	A4	
ACM	Cement sheet walls	79 PE Store	22	Refer to 33538-128	20 m <sup>2</sup>	2	1	1	2	1	7	A3	Localised damage by light switch. Encapsulate.
ACM	Cement sheet ceiling	79 PE Store	23	Refer to 33538-129, 130	10 m <sup>2</sup>	2	1	1	0	0	4	A4	
ACM	Cement sheet walls	80 PE Store	24	Refer to 33538-170	20 m <sup>2</sup>	2	1	1	0	1	5	A3	

#### 4. Extent of Damage (Condition)

Variable	Score	Example of score variables
Condition	0	No visible damage
	1	Few scratches / marks broken edges etc.
	2	Significant breakage / many areas of damage revealing loose asbestos fibres
	3	High damage / visible debris


Condition	Comments
	No Access
	No Access
	No Access
	Replaced
	Replaced
	Replaced
	Replaced

Additional comments

This form is to be completed with reference to the **Division 5 Asbestos Audit (Report dated: 6-7/4/2015)**



### Asbestos Materials Register



#### 4. Extent of Damage (Condition)


Variable	Score	Example of score variables
Condition	0	No visible damage
	1	Few scratches / marks broken edges etc.
	2	Significant breakage / many areas of damage revealing loose asbestos fibres
	3	High damage / visible debris

Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments
Multi Purpose Hall													
ACM	Cement sheet ceiling	80 PE Store		Refer to 33538-171, 172	10 m <sup>2</sup>	2	1	1	0	0	4	A4	
ACM	Cement sheet ceiling	81 Hall		Refer to 33538-101	4 m <sup>2</sup>	1	1	1	0	0	3	A4	North and south entrances.
ACM	Cement sheet fire hose cupboards	81 Hall	25	Refer to 33538-158, 159, 132	5 m <sup>2</sup>	2	1	1	2	1	7	A3	Fire hose cupboards including door. Adjacent to 75 Porch and adjacent to Chair Store 77. Damage to cupboard near 75 Porch. Encapsulate. Paint to encapsulate both unpainted cupboards.
ACM	Cement sheet infill panel	82 Porch		Refer to 33538-178	1 m <sup>2</sup>	2	1	1	0	0	4	A4	Above door. Also present to south side Porch (not numbered on plans).
ACM	Cement sheet walls	83 Male Staff		Refer to 33538-118	25 m <sup>2</sup>	2	1	1	0	1	5	A3	
ACM	Cement sheet ceiling	83 Male Staff		Refer to 33538-119, 120	6 m <sup>2</sup>	2	1	1	0	0	4	A4	
ACM	Cement sheet walls	84 Female Staff		Refer to 33538-102	25 m <sup>2</sup>	2	1	1	0	1	5	A3	
ACM	Cement sheet ceiling	84 Female Staff		Refer to 33538-103	6 m <sup>2</sup>	1	1	1	0	0	3	A4	
ACM	Cement sheet walls	85 Male		Refer to 33538-121, 122	40 m <sup>2</sup>	2	1	1	0	1	5	A3	
ACM	Cement sheet ceiling	85 Male		Refer to 33538-124	16 m <sup>2</sup>	2	1	1	0	0	4	A4	
ACM	Cement sheet cubicle partitions	85 Male	26	Refer to 33538-123	4 m <sup>2</sup>	2	1	1	0	1	5	A3	
ACM	Cement sheet walls	86 Female		Refer to 33538-104, 105	60 m <sup>2</sup>	1	1	1	0	1	4	A4	Including cistern backing.
ACM	Cement sheet ceiling	86 Female		Refer to 33538-107	15 m <sup>2</sup>	1	1	1	0	0	3	A4	
ACM	Cement sheet cubicle partitions	86 Female		Refer to 33538-108	18 m <sup>2</sup>	1	1	1	0	1	4	A4	

Additional comments



This form is to be completed with reference to the **Division 5 Asbestos Audit (Report dated: 6-7/4/2015)**




Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments	Condition	
														0	1
Multi Purpose Hall														Condition	Comments
ACM	Cement sheet infill panel	87 Porch		Refer to 33538-176	1 m²	2	1	1	0	0	4	A4	Above door.		
ACM	Cement sheet walls	88 Lobby	27	Refer to 33538-125	8 m²	2	1	1	0	1	5	A3			
ACM	Cement sheet ceiling	88 Lobby		Refer to 33538-127	3 m²	2	1	1	0	0	4	A4			
ACM	Cement sheet infill panel	88 Lobby		Refer to 33538-126	1 m²	2	1	1	0	0	4	A4			
ACM	Cement sheet infill panel	89 Porch		Refer to 33538-177	1 m²	2	1	1	0	1	5	A3			
ACM	Cement sheet walls	90 Lobby		Refer to 33538-108	20 m²	1	1	1	0	1	4	A4			
ACM	Cement sheet ceiling	90 Lobby		Refer to 33538-109	6 m²	2	1	1	0	0	4	A4			
ACM	Cement sheet walls	91 Cloak	28	Refer to 33538-110	30 m²	2	1	1	0	1	5	A3			
ACM	Cement sheet ceiling	91 Cloak		Refer to 33538-111	16 m²	2	1	1	0	0	4	A4			
ACM	Electrical Backing Board	93 Servery	29	Visual Observation	1 item	1	0	1	0	1	3	A4	East wall.		
ACM	Cement sheet walls	93 Servery		Refer to 33538-116	30 m²	2	1	1	0	1	5	A3			
ACM	Cement sheet ceiling	93 Servery		Refer to 33538-117	15 m²	2	1	1	0	0	4	A4			
ACM	Cement sheet walls	94 Bulk Store		Refer to 33538-112	30 m²	2	1	1	0	1	5	A3			
ACM	Cement sheet ceiling	94 Bulk Store		Refer to 33538-113	15 m²	2	1	1	0	0	4	A4			
ACM	Cement sheet ceiling	95 Porch		Refer to 33538-114	30 m²	1	1	1	0	0	3	A4			
ACM	Cement sheet infill panel	95 Porch		Refer to 33538-115	11 m²	2	1	1	0	1	5	A3	Infill panels below windows.		
ACM	Cement sheet infill panel	130 Covered Way		Refer 33538-174	1 m²	2	1	1	0	0	4	A4	Above door.		
ACM	Cement sheet walls	243 Store		Refer to 33538-156	2 m²	3	1	1	0	1	6	A3	No access into area due to stored items blocking the door. Previously identified in 2004 audit. Presumed still present.		No Access

### Additional comments

This form is to be completed with reference to the **Division 5 Asbestos Audit (Report dated: 6-7/4/2015)**



### Asbestos Materials Register



#### 4. Extent of Damage (Condition)

Variable	Score	Example of score variables
Condition	0	No visible damage
	1	Few scratches / marks broken edges etc.
	2	Significant breakage / many areas of damage revealing loose asbestos fibres
	3	High damage / visible debris


Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments
<b>Multi Purpose Hall</b>													
ACM	Electrical backing boards	243 Store	30	Visual Observation	2 units	1	0	1	0	1	3	A4	One within room, a second to wall above room.
ACM	Millboard lining to electrical backing board	243 Store		Refer to 33538-157	1 units	1	1	2	1	0	5	A3	
ACM	Electrical backing board	244 Store (sub level below stage area)	31	Visual Observation	1 unit	1	0	1	0	1	3	A4	To west wall.
ACM	Cement sheet walls	244 Store (sub level below stage area)	32	Refer to 33538-180, 181, 183	50 m <sup>2</sup>	1	1	1	1	1	5	A3	Unpainted. Panels to upper walls. Paint to encapsulate.
ACM	Cement sheet ceiling	244 Store (sub level below stage area)	33	Refer 33538-182	>100 m <sup>2</sup>	2	1	1	1	0	5	A3	Unpainted. No inspection to east of east side partition wall / plant.
ACM	Cement sheet partition walls	244 Store (sub level below stage area)	34	Refer 33538-180	10 m <sup>2</sup>	1	1	1	1	1	5	A3	Limited inspection within area due to stored items.
ACM	Cement sheet board	244 Store (sub level below stage area)		Refer 33538-184	10 m <sup>2</sup>	1	1	1	1	1	5	A3	Limited inspection within area due to stored items. Not identified in current audit. Previously identified in 2004 audit. Presumed still present.
ACM	Cement sheet walls	273 Control Panel		Refer 33538-147	4m <sup>2</sup>	2	1	1	0	1	5	A3	East and west walls
ACM	Cement sheet fascia panels	External	35	Visual Observation	>100 lm	1	1	1	0	0	3	A4	Fascia panels at high level above clear storey windows.
ACM	Mastic	External	36	Refer 33538-204	Unknown	1	0	1	0	1	3	A4	To expansion joints throughout.
No access was gained within 243 Store, 68 Steps and 69 Steps and within and behind walls, floors, subfloors, tiles, urinals, cavities, ceiling voids, plant/machinery, live electrics or to heights above 3m. Limited access below floor coverings, behind wall coverings and where large amounts of stored items were present. These areas may require further investigation.													
<b>Music Block</b>													
ACM	Vinyl floor tiles	99 Instruments Store	37	Refer to 33538-186x	16 m <sup>2</sup>	1	0	1	0	1	3	A4	White. Attached with black mastic/adhesive.
ACM	Vinyl floor tile adhesive	99 Instruments Store		Refer to 33538-186y	16 m <sup>2</sup>	1	0	1	0	1	3	A4	
ACM	Vinyl floor tiles	102 Corridor	38	Refer to 33538-185x	12 m <sup>2</sup>	1	0	1	1	1	4	A4	Localised damage adjacent 110 Practice Room. Attached with black mastic/adhesive. Encapsulate.
ACM	Vinyl floor tile adhesive	102 Corridor		Refer to 33538-185y	12 m <sup>2</sup>	1	0	1	0	1	3	A4	
ACM	Vinyl floor tiles	103 Office	39	Refer to 33538-187x	6 m <sup>2</sup>	1	0	1	0	1	3	A4	White. Attached with black mastic/adhesive.

Additional comments

This form is to be completed with reference to the **Division 5 Asbestos Audit (Report dated: 6-7/4/2015)**



### Asbestos Materials Register



Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments
ACM	Vinyl floor tile adhesive	103 Office		Refer to 33538-187y	8 m <sup>2</sup>	1	0	1	0	1	3	A4	
No access was gained within and behind walls, floors, subfloors, tiles, urinals, cavities, ceiling voids, plant/machinery, live electrics or to heights above 3m. Limited access below floor coverings, behind wall coverings and where large amounts of stored items were present. These areas may require further investigation.													
Science Wing													
ACM	Cement sheet wall	25 Cleaner		Refer to 33538-48	8 m <sup>2</sup>	1	1	1	0	1	4	A4	No access. Previously identified in 2004 audit to east wall. Presume still present.
ACM	Insulation to incubator	30 Store	40	Visual Observation	1 unit	2	1	1	0	1	5	A3	Labmaster incubator lining. Serial No. 7426. Asset No. 8790-4-0407 101.
ACM	Cement sheet panel and debris	33 Science	41	Refer to 33538-37	< 1 m <sup>2</sup>	2	2	1	3	1	9	A2	Cement sheet repair panel to back of cupboard. Sink cupboard on south wall. Remove. Restrict access until removed. Refer to Appendix F.
ACM	Heat mats	33 Science	42	DA7318	10 units	1	1	1	2	1	6	A3	Stored in sealed cupboard. All suspect asbestos containing mats from 30 Store, 33 Science, 35 Store and 37 Science were stored in this area. Remove. Restrict access until removed. See Appendix F.
ACM	Mastic to AC ductwork	35 Store		DA7316	< 1 m <sup>2</sup>	1	0	1	1	1	4	A4	Mastic to AC duct flange joining. Presume material to be in same application throughout the building.
ACM	Millboard lining to hotplates	35 Store	43	DA7314	3 units	1	2	2	1	2	8	A2	Lining to hotplates (x3). Stored in sealed cupboard. All portable suspect asbestos containing materials from 30 Store, 33 Science, 35 Store and 37 Science were stored in sealed cupboard - 33 Science. Remove. Restrict access until removed. See Appendix F.

4. Extent of Damage (Condition)		
Variable	Score	Example of score variables
Condition	0	No visible damage
	1	Few scratches / marks broken edges etc.
	2	Significant breakage / many areas of damage revealing loose asbestos fibres
	3	High damage / visible debris

Condition	Comments
	No Access
	Removed
	Removed
	Removed


Additional comments



This form is to be completed with reference to the **Division 5 Asbestos Audit (Report dated: 6-7/4/2015)**



### Asbestos Materials Register



Hazard Group	Description	Location	Photograph No.	Sample Number	Approx. Quantity	Asbestos Fibre Type	Surface Treatment	Product Type	Condition	Likelihood of Disturbance	Risk Score	Action Rating	Comments
<b>Science Wing</b>													
ACM	Cement sheet eaves	External		DA7309, Refer 33538-248, 299-300, 303, 305, 307	100 lm	2	1	1	0	0	4	A4	North, south and east sides.
ACM	Cement sheet clear storey eaves	External		Refer 33538-251 - 255	80 lm	2	1	1	0	0	4	A4	North and south sides.
ACM	Cement sheet porch ceilings	External		Refer 33538-304 & 306	4 m²	2	1	1	0	0	4	A4	East and west of 131 Covered Link.
No access was gained within 25 Cleaner, and behind walls, floors, subfloors, tiles, urinals, cavities, ceiling voids, plant/machinery, live electrics or to heights above 3m. Limited access to 244 Store, below floor coverings, behind wall coverings and where large amounts of stored items were present. These areas may require further investigation.													
<b>Trade Wing</b>													
ACM	Cement sheet ceiling	8 Corridor		Refer to 33538-211	50 m²	1	1	1	0	0	3	A4	Painted cream.
ACM	Internal lining to kiln	3 Clay Store	44	Visual Observation	1 unit	2	1	1	0	1	5	A3	No access to sample without damage. Asbestos presumed.
ACM	Cement sheet eaves	External		Refer to 33538-243, 279, 280, 285	40 lm	2	1	1	0	0	4	A4	Painted yellow.
ACM	Cement sheet clear storey eaves	External		Refer to 33538-245 & 246	40 lm	2	1	1	0	0	4	A4	Painted white.
No access was gained within and behind walls, floors, subfloors, tiles, urinals, cavities, ceiling voids, plant/machinery, live electrics or to heights above 3m. Limited access below floor coverings, behind wall coverings and where large amounts of stored items were present. These areas may require further investigation.													

#### 4. Extent of Damage (Condition)

Variable	Score	Example of score variables
Condition	0	No visible damage
	1	Few scratches / marks broken edges etc.
	2	Significant breakage / many areas of damage revealing loose asbestos fibres
	3	High damage / visible debris

Condition	Comments

Inspected by \_\_\_\_\_ HSR \_\_\_\_\_ Asbestos Coordinator \_\_\_\_\_ DATE \_\_\_\_\_

Additional comments